


[illegible]

Technical drawing of a door assembly kit. The drawing includes two main door panels, labeled 21 and 22. Various components are numbered and illustrated with assembly instructions:

- Top Components:** A long horizontal bar (2) is shown at the top. Below it, a bracket (4) is attached to a vertical bar (11), which is connected to a horizontal bar (14). A small component (12) is shown in a dashed box.
- Door Panels:** Two large rectangular panels, 21 and 22, are shown. Panel 21 has a vertical bar (1) on its left side and a vertical bar (6) on its right side. Panel 22 has a vertical bar (7) on its left side and a vertical bar (8) on its right side. A small component (13) is shown near panel 22.
- Bottom Components:** A bracket (4) is shown at the bottom left. A small component (12) is shown in a dashed box. A small component (3) is shown in a dashed box. A small component (10) is shown in a dashed box. A small component (9) is shown in a dashed box. A small component (5) is shown in a dashed box. A small component (10) is shown in a dashed box. A small component (20) is shown in a dashed box.
- Assembly Instructions:** A dashed box on the right side of the drawing contains a diagram of a door with an arrow pointing to the right, indicating the direction of movement. A dashed box at the bottom right contains a diagram of a door with an arrow pointing to the left, indicating the direction of movement.



Identity number
XXXXXX . XXX . XXX

XXX . 001 . XXXX

Made in Germany



0008P07001